



North Carolina Department of Environment and Natural Resources

Division of Waste Management

Dexter R. Matthews

Director

Beverly Eaves Perdue
Governor

Dee Freeman
Secretary

April 5, 2011

Mr. Ray Hoffman, P.E.
Republic Services of North Carolina, LLC
Area Engineer
1220 Commerce Street
Conover, NC 28613

RE: Monitor Well MW-8 Assessment
JMN/Cleveland Container Landfill, Permit #23-02

Dear Mr. Hoffman:

A review of groundwater analytical data from the JMN/Cleveland Container Landfill indicates exceedances of groundwater standards established in 15A NCAC 2L .0202 (2L Standards) during recent monitoring events. Tetrachloroethene and vinyl chloride have been reported at concentrations greater than their respective 2L Standards in groundwater samples collected from MW-8. Monitor well MW-8 appears to be located near the compliance boundary and industrial landfills are required to comply with the 2L standards at the compliance boundary in accordance with 15A NCAC 13B .503 (2)(d)(iv).

Republic should submit an assessment work plan to the Solid Waste Section outlining how the reported VOC contamination in MW-8 will be delineated within 60 days of receiving this correspondence.

Please contact me at (919) 508-8516 or by e-mail at ervin.lane@ncdenr.gov if you have any questions or concerns regarding this letter. Thank you in advance for your anticipated cooperation in this manner.

Sincerely,

Ervin Lane
Hydrogeologist
Environmental Compliance
Solid Waste Section

cc: Rachel P. Kirkman, P.G., Golder Associates, Inc.
Mark Poindexter, Field Operations Branch Head
Deb Aja, Western District Supervisor
C.T. Gerstell, Environmental Senior Specialist
Solid Waste Central Files